

## **Handling Instructions for Tent Fabric**

### **(ST-301, 302)**

For this high-end fabric, special handling instructions are applicable. These should be followed strictly in order to ensure the best results:

#### **Before Printing**

You should check the Fabric Inspection Report (**Table 1**) carefully before printing, and verify the printing size.

#### **During Printing**

- Compatibility levels of different inks:  
UV ink: 1. Printable 2. Unfoldable 3. Anti-scratch  
HP Latex ink: 1. Printable 2. Foldable 3. Not Anti-scratch  
Solvent ink: 1. Printable 2. Foldable 3. Not Anti-scratch  
Eco-solvent ink: 1. Printable 2. Foldable 3. Not Anti-scratch  
Heat transfer: 1. Printable 2. Foldable 3. Anti-scratch  
Direct dye-sublimation ink: 1. Printable 2. Foldable 3. Anti-scratch  
(neither color saturation nor resolution is hard to reach a ideal situation.)
- Best results achieved by heat transfer printing.

#### **Color Fixation**

For best results, high temperature and long contact time are neither necessary nor suggested to achieve good results.

**Attention:** Please do sample printing tests before regular production, as no liability will be assumed for possible damages (also after a period of time).

#### **Package and Install**

Roll pack suggested

Note: During the transportation and printing, the water-pressure resistance index will reduce.

#### **Clean**

Not washable

Not suitable for dry cleaning

Cleanable with damp cloth

To iron at low temperature


**Table 1**

### Fabric Inspection Report

Product # \_\_\_\_\_ Date \_\_\_\_\_

Width \_\_\_\_\_ Meters \_\_\_\_\_ Batch NO: \_\_\_\_\_


[ Left (L)      Center(C)      Right(R)      Across (A) ]

Defects: 

These marks mean the location of the defects on fabric width direction. Note that there will be a defect label on the Left(L),

“Across(A)” means the defects across the whole width.

It means the defect on the 31 meters counted from inside, and on the left.

1	2	3	4	5
6	7	8	9	10
11	12	13	14	15
16	17	18	19	20
21	22	23	24	25
26	27	28	29	30
31  L	32	33	34	35
36	37	38	39	40
41	42	43	44	45
46	47	48	49	50
51	52	53	54	55
56	57	58	59	60
61	62	63	64	65
66	67	68	69	70
71	72	73	74	75
76	77	78	79	80
81	82	83	84	85
86	87	88	89	90
91	92	93	94	95
96	97	98	99	100

Defects includes stain, tear/ hole, missing thread, grease and so on

**Note: Above defects are marked from inside to out. Please note when printing.**